



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	339	Date:	10/25/2004	MeterBasin:	01_WR05
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	3	Setup No:	5	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6020		Cross Country	Blvd

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 27
Setup No. 5
339

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/25/04	Start Time: 1600
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 6	Test Length: 1201'
US MH: 1520888	DS MH: 1520878	# of Blowers: 1/2/3	Ground: Dry Moderate Wet
Plugged US: Y (N)	Plugged DS: Y (N)	Plugs Removed? Y (N)	Recorder: Bob Blank
Comments:			

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004
Leader Form

Sketch No: 339

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\339.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	339	Date:	10/25/2004	MeterBasin:	01_WR05
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	4	Setup No:	5	Priority CCTV:	Y

House Number	Street Prefix:	Street Name:	Street Type:		
6018		Cross Country	Blvd		
Source Type:	16= Storm Ditch	Location:	11=Field	Severity:	4=Major
Sector:	1=Public	Drainage Area:	100		
Comments:	Priority CCTV- Defect across the street from address				

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 0

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1025-2004\T-2\PLAYER_B\B_2004_1025Image0889.JPG

Image Status: Can't find image in the specified nam

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 27
Setup No. 5
339

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/25/04	Start Time: 1600
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 6	Test Length: 1201'
US MH: 1520888	DS MH: 1520878	# of Blowers: 1/2/3	Ground: Dry Moderate Wet
Plugged US: Y (N)	Plugged DS: Y (N)	Plugs Removed? Y (N)	Recorder: Bal Blunk
Comments:			

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004
Leader Form

Sketch No: 339

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\339.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	339	Date:	10/25/2004	MeterBasin:	01_WR05
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	5	Setup No:	5	Priority CCTV:	

House Number	6016	Street Prefix:		Street Name:	Cross Country	Street Type:	Blvd
Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:	4=Major		
Sector:	2=Private	Drainage Area:	16				
Comments:							

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 890

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1025-2004\T-2\PLAYER_B\B_2004_1025Image0890.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 27
Setup No. 5
339

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/25/04	Start Time: 1600
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 6	Test Length: 1201'
US MH: 1520888	DS MH: 1520878	# of Blowers: 1/2/3	Ground: Dry Moderate Wet
Plugged US: Y (N)	Plugged DS: Y (N)	Plugs Removed? Y (N)	Recorder: Bal Blunk
Comments:			

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004
Leader Form

Sketch No: 339

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\339.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	339	Date:	10/25/2004	MeterBasin:	01_WR05
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	6	Setup No:	5	Priority CCTV:	

House Number	6016	Street Prefix:		Street Name:	Cross Country	Street Type:	Blvd
Source Type:	02= Service Line	Location:	5=Sidewalk	Severity:	3=Moderate		
Sector:	2=Private	Drainage Area:	0				
Comments:							

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 891

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1025-2004\T-2\PLAYER_B\B_2004_1025Image0891.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 29
Setup No. 5
339

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/25/04	Start Time: 1600
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 6	Test Length: 1201'
US MH: 1520888	DS MH: 1520878	# of Blowers: 1/2/3	Ground: Dry Moderate Wet
Plugged US: Y (N)	Plugged DS: Y (N)	Plugs Removed? Y (N)	Recorder: Bal Blunk
Comments:			

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004
Leader Form

Sketch No: 339

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\339.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	339	Date:	10/25/2004	MeterBasin:	01_WR05
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	7	Setup No:	5	Priority CCTV:	

House Number	6016	Street Prefix:		Street Name:	Cross Country	Street Type:	Blvd
Source Type:	01= Main Sewer	Location:	5=Sidewalk	Severity:	3=Moderate		
Sector:	1=Public	Drainage Area:	25				
Comments:							

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 892

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1025-2004\T-2\PLAYER_B\B_2004_1025Image0892.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 27
Setup No. 5
339

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/25/04	Start Time: 1600
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 6	Test Length: 1201'
US MH: 1520888	DS MH: 1520878	# of Blowers: 1/2/3	Ground: Dry Moderate Wet
Plugged US: Y (N)	Plugged DS: Y (N)	Plugs Removed? Y (N)	Recorder: Bob Blank
Comments:			

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004
Leader Form

Sketch No: 339

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\339.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	339	Date:	10/25/2004	MeterBasin:	01_WR05
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	8	Setup No:	5	Priority CCTV:	

House Number	6018	Street Prefix:		Street Name:	Cross Country	Street Type:	Blvd
Source Type:	01= Main Sewer	Location:	5=Sidewalk	Severity:	3=Moderate		
Sector:	1=Public	Drainage Area:	25				
Comments:							

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 893

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1025-2004\T-2\PLAYER_B\B_2004_1025Image0893.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 27
Setup No. 5
339

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/25/04	Start Time: 1600
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 6	Test Length: 1201'
US MH: 1520888	DS MH: 1520878	# of Blowers: 1/2/3	Ground: Dry Moderate Wet
Plugged US: Y (N)	Plugged DS: Y (N)	Plugs Removed? Y (N)	Recorder: Bal Blunk
Comments:			

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004
Leader Form

Sketch No: 339

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\339.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	339	Date:	10/25/2004	MeterBasin:	01_WR05
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	9	Setup No:	5	Priority CCTV:	

House Number	6000	Street Prefix:		Street Name:	Cross Country	Street Type:	Blvd
Source Type:	02= Service Line	Location:	5=Sidewalk	Severity:	4=Major		
Sector:	1=Public	Drainage Area:	200				
Comments:							

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 894

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1025-2004\T-2\PLAYER_B\B_2004_1025Image0894.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 27
Setup No. 5
339

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/25/04	Start Time: 1600
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 6	Test Length: 1201'
US MH: 1520888	DS MH: 1520878	# of Blowers: 1/2/3	Ground: Dry Moderate Wet
Plugged US: Y (N)	Plugged DS: Y (N)	Plugs Removed? Y (N)	Recorder: Bob Blank
Comments:			

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004
Leader Form

Sketch No: 339

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\339.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	340	Date:	10/25/2004	MeterBasin:	01_WR04
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	1	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5932		Cross Country	Blvd

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 340
Setup No. 6

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/25/04	Start Time: 1745
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 9	Test Length: 1306
US MH: 1520877	DS MH: 1521300	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugged US: Y N	Plugged DS: Y N	Comments: —	
Plugs Removed? Y N	Recorder: Bob Blank		

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004 Leader Form

Sketch No: 340

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\340.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	340	Date:	10/25/2004	MeterBasin:	01_WR04
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	2	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5934		Cross Country	Blvd

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 29
Setup No. 6
340

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/25/04	Start Time: 1745
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 9	Test Length: 1306
US MH: 1520877	DS MH: 1521300	# of Blowers: 1 2 3	Ground: (Dry) Moderate Wet
Plugged US: (Y) N	Plugged DS: Y (N)	Comments: —	
Plugs Removed? (Y) N	Recorder: Bob Blank		

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004 Leader Form

Sketch No: 340

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\340.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	340	Date:	10/25/2004	MeterBasin:	01_WR04
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	4	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5930		Cross Country	Blvd

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 39
Setup No. 6
340

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/25/04	Start Time: 1745
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 9	Test Length: 1306
US MH: 1520877	DS MH: 1521300	# of Blowers: 1 2 3	Ground: (Dry) Moderate Wet
Plugged US: (Y) N	Plugged DS: Y (N)	Comments: —	
Plugs Removed? (Y) N	Recorder: Bob Blank		

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004
Leader Form

Sketch No: 340

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\340.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	340	Date:	10/25/2004	MeterBasin:	01_WR04
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	5	Setup No:	6	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5928		Cross Country	Blvd

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 340
Setup No. 6

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/25/04	Start Time: 1745
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 9	Test Length: 1306
US MH: 1520877	DS MH: 1521300	# of Blowers: 1 2 3	Ground: (Dry) Moderate Wet
Plugged US: (Y) N	Plugged DS: (Y) N	Comments: —	
Plugs Removed? (Y) N	Recorder: Bob Blank		

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004 Leader Form

Sketch No: 340

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\340.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	340	Date:	10/25/2004	MeterBasin:	01_WR04
Observer ID:	B	Crew:	T-2	Dye Test Recommended:	N
Defect No:	6	Setup No:	6	Priority CCTV:	

House Number	5926	Street Prefix:		Street Name:	Cross Country	Street Type:	Blvd
Source Type:	01= Main Sewer	Location:	5=Sidewalk	Severity:	4=Major		
Sector:	1=Public	Drainage Area:	4000				
Comments:							

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 896

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1025-2004\T-2\PLAYER_B\B_2004_1025Image0896.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 340
Setup No. 6

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10/25/04	Start Time: 1745
Crew: T2	Street Location: Cross Country Blvd	Number of Segments: 9	Test Length: 1306
US MH: 1520877	DS MH: 1521300	# of Blowers: 1 2 3	Ground: (Dry) Moderate Wet
Plugged US: (Y) N	Plugged DS: (Y) N	Comments: —	
Plugs Removed? (Y) N	Recorder: Bob Blank		

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004 Leader Form

Sketch No: 340

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\340.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	341	Date:	10/25/2004	MeterBasin:	01_WR29
Observer ID:	A	Crew:	T-3	Dye Test Recommended:	N
Defect No:	1	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3301		Shelburne	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 25
Setup No. 1
341

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10-25-04	Start Time: 10:45
Crew: T3	Street Location: SHELburne RD. + SEVEN MILE LN.		
US MH: 1520735	DS MH: 1522649	Number of Segments: 6	Test Length: 165'
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: JAA	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

SMOKE WAS NOT GOING DOWN TO MAIN PARALLEL WORK LINE, BUT IT WAS REAPPEARING THE HOUSES JUST ABOVE THREE FEET. INCREASE A TIP IN THE LINE!

Last Revised 9/16/2004
Leader Form

Sketch No: 341

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\341.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	341	Date:	10/25/2004	MeterBasin:	01_WR29
Observer ID:	A	Crew:	T-3	Dye Test Recommended:	N
Defect No:	2	Setup No:	1	Priority CCTV:	

House Number	3313	Street Prefix:		Street Name:	Shelburne	Street Type:	ROAD
Source Type:	02= Service Line	Location:	5=Sidewalk	Severity:	3=Moderate		
Sector:	1=Public	Drainage Area:	1000				
Comments:							

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 608

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1025-2004\T-3\PLAYER_A\A_2004_1025Image0608.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 25
Setup No. 1
341

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10-25-04	Start Time: 10:45
Crew: T3	Street Location: SHELburne Rd. + SEVEN MILE Ln.		
US MH: 1520735	DS MH: 1522649	Number of Segments: 6	Test Length: 165'
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: JAA	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

SMOKE WAS NOT GOING DOWN TO MAIN PARALLEL WORK LINE, BUT IT WAS REAPPEARING THE HOUSES JUST ABOVE THREE FEET. THERE A DIP IN THE LINE?

Last Revised 9/16/2004
Leader Form

Sketch No: 341

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\341.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	341	Date:	10/25/2004	MeterBasin:	01_WR29
Observer ID:	A	Crew:	T-3	Dye Test Recommended:	N
Defect No:	3	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3314		Shelburne	ROAD

Source Type:	18= Other	Location:	14=Other	Severity:	1=No Smoke
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 25
Setup No. 1
341

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10-25-04	Start Time: 10:45
Crew: T3	Street Location: SHELburne Rd. + SEVEN MILE Ln.		
US MH: 1520735	DS MH: 1522649	Number of Segments: 6	Test Length: 165'
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: JAA	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

SMOKE WAS NOT GOING DOWN TO MAIN PARALLEL WORK LINE, BUT IT WAS REAPPEARING THE HOUSES JUST ABOVE THREE FEET. THERE A DIP IN THE LINE?

Last Revised 9/16/2004
Leader Form

Sketch No: 341

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\341.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	341	Date:	10/25/2004	MeterBasin:	01_WR29
Observer ID:	A	Crew:	T-3	Dye Test Recommended:	N
Defect No:	4	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3314		Shelburne	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	2=Trace
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 25
Setup No. 1
341

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10-25-04	Start Time: 10:45
Crew: T3	Street Location: SHELBOURNE RD. + SEVEN MILE LN.		
US MH: 1520735	DS MH: 1522649	Number of Segments: 6	Test Length: 165'
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: JAA	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

SMOKE WAS NOT GOING DOWN TO MAIN PARALLEL WORK LINE, BUT IT WAS REAPPEARING THE HOUSES JUST ABOVE THREE FEET. THERE A DIP IN THE LINE?

Last Revised 9/16/2004
Leader Form

Sketch No: 341

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\341.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	341	Date:	10/25/2004	MeterBasin:	01_WR29
Observer ID:	A	Crew:	T-3	Dye Test Recommended:	N
Defect No:	5	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3305		Seven Mile	LANE

Source Type:	04= Cleanout	Location:	4=Driveway	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 25
Setup No. 1
341

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10-25-04	Start Time: 10:45
Crew: T3	Street Location: SHELburne Rd. + SEVEN MILE Ln.		
US MH: 1520735	DS MH: 1522649	Number of Segments: 6	Test Length: 165'
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: JAA	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

SMOKE WAS NOT GOING DOWN TO MAIN PARALLEL WORK LINE, BUT IT WAS REACHING THE HOUSES JUST ABOVE THESE FIVE. THERE A DIP IN THE LINE?

Last Revised 9/16/2004
Leader Form

Sketch No: 341

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\341.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	341	Date:	10/25/2004	MeterBasin:	01_WR29
Observer ID:	A	Crew:	T-3	Dye Test Recommended:	N
Defect No:	6	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3401		Seven Mile	LANE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 25
Setup No. 1
341

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10-25-04	Start Time: 10:45
Crew: T3	Street Location: SHELBOURNE RD. + SEVEN MILE LN.		
US MH: 1520735	DS MH: 1522649	Number of Segments: 6	Test Length: 165'
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: JAA	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

SMOKE WAS NOT GOING DOWN TO MAIN PARALLEL WORK LINE, BUT IT WAS REAPPEARING THE HOUSES JUST ABOVE THREE FEET. INCREASE A TIP IN THE LINE!

Last Revised 9/16/2004
Leader Form

Sketch No: 341

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\341.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	341	Date:	10/25/2004	MeterBasin:	01_WR29
Observer ID:	A	Crew:	T-3	Dye Test Recommended:	N
Defect No:	7	Setup No:	1	Priority CCTV:	

House Number	3400	Street Prefix:		Street Name:	Seven Mile	Street Type:	LANE
Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major		
Sector:	2=Private	Drainage Area:	50				
Comments:							

SMOKE TEST PHOTOS



Photo No:

Filename Path:

Image Status: No image name specified.

Photo No: 609

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1025-2004\T-3\PLAYER_A\A_2004_1025Image0609.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 25
Setup No. 1
341

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10-25-04	Start Time: 10:45
Crew: T3	Street Location: SHELburne Rd. + SEVEN MILE Ln.		
US MH: 1520735	DS MH: 1522649	Number of Segments: 6	Test Length: 165'
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: JAA	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

SMOKE WAS NOT GOING DOWN TO MAIN PARALLEL WORK LINE, BUT IT WAS REAPPEARING THE HOUSES JUST ABOVE THREE FEET. INCREASE A TIP IN THE LINE!

Last Revised 9/16/2004
Leader Form

Sketch No: 341

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\341.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	341	Date:	10/25/2004	MeterBasin:	01_WR29
Observer ID:	A	Crew:	T-3	Dye Test Recommended:	N
Defect No:	8	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3503		Seven Mile	LANE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 25
Setup No. 1
341

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10-25-04	Start Time: 10:45
Crew: T3	Street Location: SHELBOURNE RD. + SEVEN MILE LN.		
US MH: 1520735	DS MH: 1522649	Number of Segments: 6	Test Length: 165'
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry <input type="radio"/> Moderate <input type="radio"/> Wet
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: JAA	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

SMOKE WAS NOT GOING DOWN TO MAIN PARALLEL WORK LINE, BUT IT WAS REAPPEARING THE HOUSES JUST ABOVE THREE FEET. THERE A DIP IN THE LINE?

Last Revised 9/16/2004
Leader Form

Sketch No: 341

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\341.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	342	Date:	10/25/2004	MeterBasin:	01_WR33
Observer ID:	A	Crew:	T-3	Dye Test Recommended:	N
Defect No:	1	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3400		Hatton	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:



Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

				Page <u>1</u> of <u>2</u>	
BUREAU OF WATER AND WASTEWATER				Smoke Set No. <u>25</u>	
SMOKE TEST INSPECTION FORM				Setup No. <u>2</u>	
342.					
TEST LOCATION					
Project: WRPA	Sewershed: Jones Falls	Date: 10-25-04	Start Time: 1205		
Crew: T3	Street Location: KERAK RD				
US MH: 1520770	DS MH: 1520768 1520758	Number of Segments: 6	Test Length: 954'		
Plugged US: Y <input checked="" type="radio"/> N	Plugged DS: Y <input checked="" type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry Moderate Wet		
Plugs Removed? Y <input checked="" type="radio"/> N	Recorder: JWM	Comments:			
FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)					
					
CREW COMMENTS					
Last Revised 9/16/2004					
Leader Form					

Sketch No: 342

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\342.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	342	Date:	10/25/2004	MeterBasin:	01_WR33
Observer ID:	A	Crew:	T-3	Dye Test Recommended:	N
Defect No:	2	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3301		Nerak	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:



Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

				Page <u>1</u> of <u>2</u>	
BUREAU OF WATER AND WASTEWATER				Smoke Set No. <u>25</u>	
SMOKE TEST INSPECTION FORM				Setup No. <u>2</u>	
342.					
TEST LOCATION					
Project: WRPA	Sewershed: Jones Falls	Date: 10-25-04	Start Time: 1205		
Crew: T3	Street Location: KERAK RD				
US MH: 1520770	DS MH: 1520758 1520759	Number of Segments: 6	Test Length: 954'		
Plugged US: Y <input checked="" type="radio"/> N	Plugged DS: Y <input checked="" type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry Moderate Wet		
Plugs Removed? Y <input checked="" type="radio"/> N	Recorder: JWM	Comments:			
FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)					
					
CREW COMMENTS					
Last Revised 9/16/2004					
Leader Form					

Sketch No: 342

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\342.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	342	Date:	10/25/2004	MeterBasin:	01_WR33
Observer ID:	A	Crew:	T-3	Dye Test Recommended:	N
Defect No:	3	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3302		Nerak	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.




SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland


FIELD SKETCH

Page 1 of 2
Smoke Set No. 25
Setup No. 2
342.

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10-25-04	Start Time: 1205
Crew: T3	Street Location: KERAK RD		
US MH: 1520770	DS MH: 1520758 1520759	Number of Segments: 6	Test Length: 954'
Plugged US: <input checked="" type="radio"/> Y <input type="radio"/> N	Plugged DS: <input checked="" type="radio"/> Y <input type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry Moderate Wet
Plugs Removed? <input checked="" type="radio"/> Y <input type="radio"/> N	Recorder: JWM	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)



CREW COMMENTS

Last Revised 9/16/2004Leader Form

Sketch No: 342

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\342.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	342	Date:	10/25/2004	MeterBasin:	01_WR33
Observer ID:	A	Crew:	T-3	Dye Test Recommended:	N
Defect No:	4	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3213		Nerak	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	2=Trace
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:



Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

			
BUREAU OF WATER AND WASTEWATER SMOKE TEST INSPECTION FORM			
Page 1 of 2 Smoke Set No. 25 Setup No. 2 342			
TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10-25-04	Start Time: 1205
Crew: T3	Street Location: KERAK RD		
US MH: 1520770	DS MH: 1520768 1520758	Number of Segments: 6	Test Length: 954'
Plugged US: Y N	Plugged DS: Y N	# of Blowers: 1 2 3	Ground: Dry Moderate Wet
Plugs Removed? Y N	Recorder: JWM	Comments:	
FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)			
			
CREW COMMENTS			
Last Revised 9/16/2004			
Leader Form			

Sketch No: 342

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\342.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	342	Date:	10/25/2004	MeterBasin:	01_WR33
Observer ID:	A	Crew:	T-3	Dye Test Recommended:	N
Defect No:	5	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3220		Nerak	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.

Photo No:

Filename Path:

Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH

Page 1 of 2
Smoke Set No. 25
Setup No. 2
342.

**BUREAU OF WATER AND WASTEWATER
SMOKE TEST INSPECTION FORM**

TEST LOCATION			
Project: WRPA	Sewershed: Jones Falls	Date: 10-25-04	Start Time: 1205
Crew: T3	Street Location: KERAK RD		
US MH: 1520770	DS MH: 1520758 1520759	Number of Segments: 6	Test Length: 954'
Plugged US: Y <input checked="" type="radio"/> N	Plugged DS: Y <input checked="" type="radio"/> N	# of Blowers: 1 2 3	Ground: <input checked="" type="radio"/> Dry Moderate Wet
Plugs Removed? Y <input checked="" type="radio"/> N	Recorder: JWM	Comments:	

FIELD SKETCH (Show manholes and ID numbers, blower placement, source defect number, bldgs & street addresses, sandbag locations, etc.)

CREW COMMENTS

Last Revised 9/16/2004Leader Form

Sketch No: 342

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\342.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.